

**Dear Customer,**

With this INFINEON Technologies Information Note we would like to inform you about the following

**Datasheet Update in Package-Outline Drawing affecting TLS102B0MB and TLS105B0MB**

N° 106/18

## Datasheet Update in Package-Outline Drawing affecting TLS102B0MB and TLS105B0MB

► **Products affected:** Please refer to attached affected product list 1\_cip10618

► **Detailed Change Information:**

**Subject:** Datasheet Update in Package-Outline Drawing affecting TLS102B0MB and TLS105B0MB

**Reason:** correction of wrong package outline tolerances drawing

<b>Description:</b>	<u>Old</u>	<u>New</u>
<b>Package-Outline Drawing</b>	■ negative tolerance value: +0,05	■ negative tolerance value: -0,05
	■ no distance specified between pin1 and pin3	■ distance specified between pin1 and pin3

► **Product Identification:** not applicable

► **Impact of Change:** no change of process; update of documentation only

► **Attachments:** Affected product list 1\_cip10618

► **Intended start of delivery:** not applicable

If you have any questions, please do not hesitate to contact your local Sales office.

**Information Note N° 106/18**

**Datasheet Update in Package-Outline Drawing affecting TLS102B0MB and  
TLS105B0MB**



<b>Sales name</b>	<b>SP number</b>	<b>OPN</b>	<b>Package</b>
TLS102B0MB	SP001649012	TLS102B0MBHTSA1	PG-SCT595-5
TLS105B0MB	SP001588610	TLS105B0MBHTSA1	PG-SCT595-5